

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Pat Ellis	
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 230-0077	
Facility Name Antelope SWD 8" Lateral Line	Facility Type 8" SWD Line	
Surface Owner: State	Mineral Owner	Lease No. B-3627

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	36	17S	31E					Eddy

Latitude N 32 47.503° Longitude W 103 49.432°

NATURE OF RELEASE

Type of Release: Produced Fluid	Volume of Release 80 bbls	Volume Recovered 0 bbls
Source of Release: 8" SWD line	Date and Hour of Occurrence 08/17/2010	Date and Hour of Discovery 08/17/2010 3:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Josh Russo	Date and Hour 8/17/10 10:06 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

A 10" section on the 8" SWD line became uncovered and exposed to the weather which weakened the pipe causing it to rupture. The rupture section of the pipe has been removed and replaced with new pipe.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected and assessed the spill area for extents. A work plan was submitted for the remediation of the soils. The soils exceeding RRAL and the elevated chlorides were removed and transported to proper disposal. Once excavated to the appropriate depths, Tetra Tech prepared a closure report and submitted to the NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (agent for COG)		Approved by District Supervisor: 	
Title: Project Manager		Approval Date: 3/13/15	Expiration Date: N/A
E-mail Address: Ike.Tavarez@TetraTech.com		Conditions of Approval: Final	
Date: 9-24-12 Phone: (432) 682-4559		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-477