

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 02 2014

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1507736778 OPERATOR ☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC <u>229137</u>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Myox 28 State #2H	Facility Type: Flowline

Surface Owner: State	Mineral Owner: State	API No. 30-015-39060
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	28	25S	28E	330'	South	330'	West	Eddy

Latitude 32.0942178640043 Longitude -104.099595101218

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: Unknown	Volume Recovered: 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 9/19/2014 10:00 am	Date and Hour of Discovery: 9/19/2014 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Robert McNeill	Date and Hour: 9/22/2014 8:00 am (phone call)	
Was a Watercourse Reached? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse. Unknown	

If a Watercourse was Impacted, Describe Fully.\*  
Torrential rains caused flood waters to rise. Waters caused a flowline carrying produced water to break. Wells had been shut in as precaution to the rain. An unknown volume of produced water was washed away in flood waters.

Describe Cause of Problem and Remedial Action Taken.\*

The flowline was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area shows no signs of brine impact.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>A. Trujillo</u>	Signed By <u>Mike Bratcher</u>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <u>3/18/15</u>	Expiration Date: <u>NIA</u>
E-mail Address: <u>atrujillo@concho.com</u>	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: October 2, 2014	Phone: 575-748-6940	

\* Attach Additional Sheets If Necessary

2RP-2864