

MAR 26 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submitted to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB15085523A2

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Scared Hawk State Com #1	Facility Type: Well

Surface Owner: State	Mineral Owner:	API No. 30-015-35102
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	4	25S	28E	330	North	25	East	Eddy

Latitude 32.1656354310364 Longitude -104.083854368812

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 bbls PW	Volume Recovered: 5 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 3/8/2015 11:00 am	Date and Hour of Discovery: 3/8/2015 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 3/9/2015 5:49 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when the weld in a poly flowline failed to hold. Vacuum trucks were dispatched to recover any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The impacted area occurred within the pasture and road, approximately 150' x 90'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Printed Name: Amanda Trujillo	Approval Date: <i>3/26/15</i>	Expiration Date: <i>N/A</i>
Title: Senior Environmental Coordinator	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
E-mail Address: <i>atrujillo@concho.com</i>	Remediation per O.C.D. Rules & Guidelines	
Date: March 25, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: *4/26/15*

2 RP-2918