

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

Approved by appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**NAB 1509855020**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Unit Com #13H	Facility Type: Well



Surface Owner: State	Mineral Owner: State	API No. 30-015-37427
----------------------	----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	15	26S	28E	660	North	330'	West	Eddy

Latitude 32.0479055939123 Longitude -104.082877725172

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 20 bbls PW	Volume Recovered: 15 bbls PW
Source of Release: 4" Poly Flowline	Date and Hour of Occurrence: 3/19/2015 1:00 pm	Date and Hour of Discovery: 3/19/2015 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* 4" Poly connection on a flowline between two wells started to leak due to corrosion. Vacuum trucks were dispatched to the standing fluid and repairs were made.		
Describe Area Affected and Cleanup Action Taken.* The impacted area is approximately 40' x 20' in the pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 4/8/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: April 6, 2015 Phone: 575-748-6940	SUBMIT REMEDIATION PROPOSAL NO. 518/15	

\* Attach Additional Sheets If Necessary

LATER THAN: 5/8/15

2RP-2938