

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

APR 09 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1510028480

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production	<i>LP137</i>	Contact Dan Suniga
Address 6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No. 575.390.5850
Facility Name Cochiti 28 Fed 1		Facility Type SWD

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-30113
--------------------------	--------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	28	23S	29E	1980	FNL	660	FWL	Eddy

Latitude: 32.27764 Longitude: -103.99591

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 15 BBL	Volume Recovered 15 BBL
Source of Release Tanks ran over	Date and Hour of Occurrence 4.6.15 11:00 am	Date and Hour of Discovery 4.6.15 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher OCD Jeff Robertson BLM	
By Whom? Wesley Ryan	Date and Hour 4.6.15 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A transfer pump and injection pump could not keep up with production causing the tanks to run over resulting in a 15bbl spill of produced water within the lined containment.

Describe Area Affected and Cleanup Action Taken.*
A vacuum company was called out and they vacuumed up 15 BBL of produced water. Confirmed lining in containment was secure and no holes were found.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Signed By: <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 4/10/15	Expiration Date:
E-mail Address: Jeanette.barron@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 4.9.15 Phone: 575.748.1813		

Attach Additional Sheets If Necessary

2RP-2940