

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAY 21 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1514134498

OPERATOR

Initial Report Final Report

| | | |
|---|-------------|--------------------------------------|
| Name XTO ENERGY INC. | <i>5380</i> | Contact Sherry Pack |
| Address 200 N. LORAIN, STE. 800 | | Telephone No. 432.620.6709 |
| Facility Name Nash 42 | | Facility Type Battery |

| | | |
|---|---|--------------------------------|
| Surface Owner XTO ENERGY INC. | Mineral Owner XTO ENERGY INC. | API No. <i>30-015-21277</i> |
|---|---|--------------------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|-----------|------------|------------|---------------|------------------|---------------|----------------|-------------|
| H | 13 | 23S | 29E | 1980 | N | 660 | E | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|--|---|
| Type of Release Flaring | Volume of Release 12564 mcf | Volume Recovered |
| Source of Release casinghead gas | Date and Hour of Occurrence 5/4/15 | Date and Hour of Discovery 5/7/15 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher and Heather Patterson | |
| By Whom? Patty Urias | Date and Hour 5/5/15 *4/17/15 @ 9:28 am | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully. *

Describe Cause of Problem and Remedial Action Taken. *

Enterprise compressor issues caused us to flare 6589mcf and 72 hours.

Describe Area Affected and Cleanup Action Taken. *

Flaring is being used to minimize emissions

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

| | | |
|--|--|-----------------------------------|
| Signature: <i>Patty Urias</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Patty | Approved by Environmental Specialist: <i>[Signature]</i> | |
| Title: Regulatory Analyst | Approval Date: 5/21/15 | Expiration Date: N/A |
| E-mail Address: patty_urias@xtoenergy.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 5/21/2015 | Phone: 432.620.4318 | |

* Attach Additional Sheets If Necessary

2RP-2962