

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA81516753239 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production <u>6137</u>	Contact Randy Gladden
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.513.9463
Facility Name Todd 24-B Battery 2	Facility Type OIL

Surface Owner BLM	Mineral Owner BLM	API No. 30-015-27691
-------------------	-------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	24	23S	31E	660	North	1980	East	EDDY

Latitude: 32.29523 Longitude: -103.72888

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 80 BBL	Volume Recovered 75 BBL
Source of Release A water transfer pump went down causing water tank to overflow.	Date and Hour of Occurrence 2.23.15 4:00 am	Date and Hour of Discovery 2.23.15 11:10 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson BLM Mike Bratcher OCD	NM OIL CONSERVATION ARTESIA DISTRICT JUN 15 2015 RECEIVED
By Whom? Randy Gladden	Date and Hour 2.23.15 @ 11:20 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Result of transfer pump not operating properly approximately 80 barrels of produced water spilled inside containment. Lobo trucking recovered 75 BBLS and the transfer pump was repaired and returned to normal operations.		
Describe Area Affected and Cleanup Action Taken.* Unlined Containment 15x80 all inside containment. Environmental service will be called on.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>6/16/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Jeanette.barron@dvn.com</u>	Conditions of Approval:	
Date: <u>2.26.15</u> Phone: <u>575.748.1813</u>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>7/17/15</u>	

* Attach Additional Sheets If Necessary

2RP-3051