

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87404
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-14
Revised August 8, 201

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

0AB1516728054 **200737** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake Unit CVX JV RR #005H Battery	Facility Type: Exploration and Production

Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-37938
------------------------------------	------------------------------------	----------------------

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	32	25S	30E	175	South	400	East	Eddy

Latitude 32.07988° Longitude -103.89590°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10 bbls	Volume Recovered None
Source of Release Water Transfer Pump	Date and Hour of Occurrence Date and Time Unknown	Date and Hour of Discovery 6/4/2015 approx. 11:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Air eliminator failed and caused water to be released to ground within earthen containment. Air eliminator was repaired.		
Describe Area Affected and Cleanup Action Taken.* Leak affected approximately 375 square feet of caliche pad within bermed area. Impacted area will be delineated and addressed. Water transfer pumps will be placed in zero-permeability containment.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Signed By: 	
Title: Assistant Remediation Foreman	Approved by Environmental Specialist:	
E-mail Address: ACRuth@basspet.com	Approval Date: 6/15/15	Expiration Date: N/A
Date: 6/10/2015	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Phone: 432-661-0571	Attached <input type="checkbox"/>	
SUBMIT REMEDIATION PROPOSAL NO		
LATER THAN: 7/17/15		

Attach Additional Sheets If Necessary

2RD-3048