

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1516756346		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Cimarex Energy 1102683		Contact Christine Alderman		
Address 600 N Marienfeld Ste 600 Midland TX		Telephone No. 432-853-7059		
Facility Name Parkway State Com 5Y		Facility Type production		
Surface Owner		Mineral Owner	API No. 30-015-38499	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	15	19S	29E	405	N	1980	W	Eddy

Latitude 32.667114 Longitude -104.064786

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 105 bbls	Volume Recovered 5 bbls
Source of Release tank	Date and Hour of Occurrence 6/14/15 pm	Date and Hour of Discovery 6/14/15 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/ Heather Patterson	
By Whom? Christine Alderman	Date and Hour 6/15/15 1:20pm	NM OIL CONSERVATION ARTESIA DISTRICT JUN 15 2015
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
RECEIVED		
Describe Cause of Problem and Remedial Action Taken.* Lightning struck a produced water storage tank. The tank was blown out of containment but no fire is evident. The oil tanks were isolated and were not affected.		
Describe Area Affected and Cleanup Action Taken.* location pad 300' x 150' Pasture 100' x 30' Talon LPE is going to assess and develop workplan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Christine Alderman	OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman	Approved by Environmental Specialist: [Signature]	
Title: ESH Supervisor	Approval Date: 6/16/15	Expiration Date: N/A
E-mail Address: calderman@cimarex.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/15/15 Phone: 432-853-7059	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/17/15

2RP-3052