

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1516753933

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: COG Operating LLC 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: SRO State Com #60H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-41741
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter H	Section 10	Township 26S	Range 28E	Feet from the 2450'	North/South Line North	Feet from the 380'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.0576082369794 Longitude -104.067819335121

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 70 bbls Oil; 30 bbls PW	Volume Recovered: 60 bbls Oil; 20 bbls PW
Source of Release: Dump Valve FWKO	Date and Hour of Occurrence: 5/29/2015 8:30am	Date and Hour of Discovery: 5/29/2015 8:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Fri 5/29/2015 5:30 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 15 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a gasket failed on a FWKO. Vacuum trucks were dispatched to recover all standing fluid and repairs were made.

Describe Area Affected and Cleanup Action Taken.*

This release occurred with a lined facility. The facility was pressure washed and impacted gravel replaced. This facility was able to be put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Amanda Trujillo

Title: Senior Environmental Coordinator

E-mail Address: atrujillo@concho.com

Date: June 15, 2015

Phone: 575-748-6940

Approved by Environmental Specialist:

Approval Date: 6/11/15

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3050