

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1517337233 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company Linn Operating Inc. 2149324	Contact E.L. Gonzales
Address 2130 W Bender Blvd Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name Russell Turner Injection Plant (Turner B 95) closest well	Facility Type Water Station
Surface Owner Federal	Mineral Owner
API No. closest well 30-015-26612	

LOCATION OF RELEASE

Unit Letter L	Section 20	Township 17S	Range 31E	Feet from the 2610	North/South Line South	Feet from the 1000	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.8199711236509 Longitude -103.897239412252

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20bbls	Volume Recovered 10 bbls
Source of Release FG- pipeline	Date and Hour of Occurrence 06/15/2015	Date and Hour of Discovery 06/15/2015 2:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUN 18 2015

RECEIVED



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Received Alarm from Russell Turner on low discharge, went to water plant and noticed one of gauges on header was showing low pressure, immediately shut in master valve to stop line leak.

Describe Area Affected and Cleanup Action Taken.* Leak was approx. 200 Yds. North of water station measured 10 ft. long x 5ft. wide. Leak ran southwest about 250ft.x4ft.wide.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: E.L. Gonzales	Approval Date: 6/22/15	Expiration Date: N/A
Title: Production Supervisor	Conditions of Approval:	
E-mail Address: elgonzales@linenergy.com	Remediation per O.C.D. Rules & Guidelines	
Date: 06/18/2015 Phone: 505-504-8002	Attached <input type="checkbox"/>	

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 7/24/15

2RP-3058

* Attach Additional Sheets If Necessary