

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1517339929 OPERATOR ☒ Initial Report ☐ Final Report

| | | | |
|-----------------|------------------------------------|---------------|----------------------|
| Name of Company | Linn Operating Inc. 249324 | Contact | E.L. Gonzales |
| Address | 2130 W Bender Blvd Hobbs, NM 88240 | Telephone No. | 575-738-1739 |
| Facility Name | Turner A #43 | Facility Type | Oil Producer |
| Surface Owner | Federal | Mineral Owner | API No. 30-015-28793 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| P | 18 | 17S | 31E | 50 | South | 1250 | East | Eddy |

Latitude 32.8274123769042 Longitude -103.904628477667

NATURE OF RELEASE

| | | | | | |
|-----------------------------|--|---|---------------|----------------------------|--------------------|
| Type of Release | Oil / Produced Water | Volume of Release | 2bbls / 6bbls | Volume Recovered | 2bbls / 4bbls |
| Source of Release | Stuffing box | Date and Hour of Occurrence | 06/15/2015 | Date and Hour of Discovery | 06/15/2015 11:30pm |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | | Date and Hour | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

NM OIL CONSERVATION
ARTESIA DISTRICT
JUN 18 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Packing of stuffing box was wore out, made a small mess. Spilled about 8bbls. Of oil and produce water, and rain water mixture on the ground. The spill was on the south side of the pumping unit about 20 ft. long and about 15 ft. wide. The spill was contained by a berm around the location.

Describe Area Affected and Cleanup Action Taken.* Vacuum truck suck up the mess and take it to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|--|----------------------|--|
| Signature: | OIL CONSERVATION DIVISION | | |
| Printed Name: E.L. Gonzales | Approved by Environmental Specialist: | | |
| Title: Production Supervisor | Approval Date: 6/20/15 | Expiration Date: N/A | |
| E-mail Address: elgonzales@linenergy.com | Conditions of Approval: | | |
| Date: 06/18/2015 Phone: 505-504-8002 | Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 7/24/15 | | |

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3059