

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1517027403

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Chevron BOT #5H Battery	Facility Type Battery	

Surface Owner Fee	Mineral Owner Fee	API No. 30-015-37786
----------------------	----------------------	-------------------------

LOCATION OF RELEASE

Unit Letter J	Section 5	Township 24S	Range 29E	Feet from the 2310	North/South Line South	Feet from the 2310	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.24573 Longitude 104.00505

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 7 B/O	Volume Recovered 0 B/O
Source of Release Circulating pump	Date and Hour of Occurrence 6/1/2015; AM	Date and Hour of Discovery 6/1/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUN 17 2015

If a Watercourse was Impacted, Describe Fully.*

RECEIVED



Describe Cause of Problem and Remedial Action Taken.*

The circulating pump leaked, causing the release. The pump was turned off and repairs made to the pump.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 35'X 20' was affected within the lined/bermed battery. The circulating pump was turned off and the suction and discharge were closed on the pump. The impacted gravel (including the 7 B/O) was excavated /hauled to a NMOCD approved facility. Depth to Ground Water: 50-90' (approximately 65', per ChevronTexaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on the battery being lined/bermed and all released oil removed with impacted gravel, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by Environmental Specialist: 	
Title: NM Environmental Regulatory Supervisor	Approval Date: <u>6/18/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>FINAL</u>	Attached <input type="checkbox"/>
Date: June 17, 2015	Phone: 575-748-4217	2RP-

* Attach Additional Sheets If Necessary

2RP-3055