

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520454469

OPERATOR

Initial Report Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Griffin
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Loving AIB State #16	Facility Type Battery	

Surface Owner State	Mineral Owner State	API No. 30-015-35449
------------------------	------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	16	23S	28E	1650	South	990	West	Eddy

Latitude 32.30234 Longitude 104.09736

NATURE OF RELEASE

Type of Release Crude Oil & Produced Water	Volume of Release 1 B/O & 4 B/PW	Volume Recovered 0 B/O & 3 B/PW
Source of Release 2" Line	Date and Hour of Occurrence 7/8/2015; AM	Date and Hour of Discovery 7/8/2015; AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 20 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
There was a pin hole on a 2" line off of the wellhead, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 10' X 50'. The well was shut in, a vacuum truck was called to recover the released fluids, and repairs were made to the 2" line. Impacted soils excavated /hauled to a NMOCD approved facility. Depth to Ground Water: < 50' (approximately 35', per Chevron/Texaco Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on most of the released fluid recovered and repairs made to the poly line, Yates Petroleum Corporation requests closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Griffin</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Griffin	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Agent	Approval Date: <u>7/23/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>ACannon@yatespetroleum.com</u>	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: July 20, 2015 Phone: 575-748-4111	2RP-	

* Attach Additional Sheets If Necessary

2RP-3148