

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 22 2015 Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
Revised August 8, 2011 with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1526726050 OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 008H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 3001539508
------------------------	------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	14	25S	30E	300		1980		Eddy

Latitude: 32.124005 Longitude: 103.853969

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 234 barrels	Volume Recovered: 190 barrels
Source of Release: Cracked head on triplex pump	Date and Hour of Occurrence: 9-21-15 @ 8:00am	Date and Hour of Discovery: 9-21-15 @ 8:44am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher via Email	
By Whom? Bradley Blevins	Date and Hour: 9-21-15 @ 10:52am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
BOPCO EHS was notified of a release that occurred when the head on the triplex pump cracked. Produced water was released to the pump containment causing the containment to overflow to the well pad.

Describe Area Affected and Cleanup Action Taken.*
A vacuum truck was called to the location and was able to recover 190 barrels of the fluid. (186 barrels from the containment and 4 barrels PW from the ground).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>9/23/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>9-22-15</i> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *10/25/15*

2RP-3294