

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-20945

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Bass Enterprises Production Co.	Contact Cindi Goodman
Address P. O. Box 2760 Midland, TX 79702	Telephone No. (432)683-2277
Facility Name BIG EDDY UNIT #39	Facility Type PUMPING UNIT STUFFING BOX

Surface Owner BLM	Mineral Owner BLM	Lease No. LC-059365
-------------------	-------------------	---------------------

LOCATION OF RELEASE

Unit Letter G	Section 29	Township 21S	Range 28E	Feet from the 1980	North/South Line NORTH	Feet from the 1980	East/West Line EAST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.45299 Longitude 104.10629

NATURE OF RELEASE

Type of Release PRODUCED WATER	Volume of Release 1 BBL	Volume Recovered 1 BBL
Source of Release STUFFING BOX	Date and Hour of Occurrence N/A	Date and Hour of Discovery 10/12/05
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

RECEIVED

OCT 27 2005

OCU-ARTESIA

If a Watercourse was Impacted, Describe Fully.\*  
NO



Describe Cause of Problem and Remedial Action Taken.\*

STUFFING BOX LEAKED FILLING CELLAR WITH PRODUCED WATER. REPAIRED STUFFING BOX, DUG 3' DOWN TO DRY DIRT, AND FILLED CELLAR WITH 3/8" CRUSHED ROCK.

Describe Area Affected and Cleanup Action Taken.\*

CELLAR FILLED WITH PRODUCED WATER. VACUUMED OUT CELLAR AND SENT TO DISPOSAL.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Cindi Goodman		Approved by District Supervisor: <b>TIM GUN</b> by MB 	
Title: Production Clerk		Approval Date: 11/4/05	Expiration Date: N/A
E-mail Address: cdgoodman@basspet.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 10/25/2005 Phone: (432)683-2277			

\* Attach Additional Sheets If Necessary