District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Revised October 10, 2003 Submit 2 Copies to appropriate

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-05385 Release Notific	ation and Co	orrective A	ction .		
OP		ГOR	☐ Initi	al Report 🛛 Final Repor	
Name of Company Hudson Oil Company of Texas	Contact J.				
Address Box 9, Maljamar, New Mexico 88264		Telephone No. 505-365-8064			
Facility Name Puckett A #9	Facility Type	e Oil Well		7.1.	
Surface Owner Federal Mineral Owner Federal Lease No. LC-029415A					
LOCATION OF RELEASE					
Unit Letter Section Township Range Feet from the	North/South Line	Feet from the	East/West Line	County	
F 24 17 31 1980	North	1980	West	Eddy	
LatitudeLongitude					
NATURE OF RELEASE					
Type of Release Oil & Produced Water		Volume of Release 5-6 Bbis Volume Recovered None			
Source of Release Wellhead - Flowline		Date and Hour of Occurrence Date and Hour of Discovery			
Was Immediate Notice Given?  ☐ Yes ☐ No ☒ Not Required ☐ If YES, To Whom?					
By Whom?	Date and I	Iour	· · · · · · · · · · · · · · · · · · ·		
Was a Watercourse Reached?	If YES, V	If YES, Volume Impacting the Watercourse.			
☐ Yes ☒ No RECEIVED					
If a Watercourse was Impacted, Describe Fully.*					
FEB 2 4 2006					
				ach-wulesia	
	****				
Describe Cause of Problem and Remedial Action Taken.*					
Well head area caused by minor well head packing leaks - other area due to flowline leak. Flowline has been repaired as well as well head.					
Wen head area caused by minor wen nead packing loaks - other area due to nowline leak. Flownite has been repaired as wen nead.					
Describe Anna ACC et la 1711 de					
Describe Area Affected and Cleanup Action Taken.*					
Well head area in cellar – and area where old drill pit was located. Cellar dug out and material blended and tilled in pit area with fertilizer and					
sand.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws and/or regulations.	report does not renev	e are operann or	responsibility for (	compilative with any other	
·		OIL CONSERVATION DIVISION			
NO 8					
Signature: B. Smill			_		
Printed Name: J.B. Smith	Approved by	District Supervis	or:	DY MB CB	
Title: Field Superintendent	Approval Da	te: 3/7/00	Expiration	Date:	
E-mail Address:	Conditions o	f Approval:		Attached	
Date: 2/23/2006 Phone: 505-365-8064				Round	
Attach Additional Sheets If Necessary		<del></del>	<del> </del>		