FAX NO. :817 334 0442

District I
1625 N: French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazus Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fc, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

30-015-05386 Release Notification and Corrective Action											
OPERATOR											Line I Dane
Name of Company Hudson Oil Company of Texas						Contact J.			man report		Final Repor
Address Box 9, Maljamar, New Mexico 88264						Telephone No. 505-365-8064					
Facility Name Puckett A #10						Facility Type Oil Well					
Surface Owner Federal Mineral Owner						Federal		Lease No. LC-029415A			
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the		NSouth Line	Feet from the	East/West Line County			777
E	24	17	31	1980	Nor	<u>th</u>	660	West	West Eddy		
			Lat	titude	Longitud	e	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
Type of Release Oil & Produced Water Volume of Release 6.8 Bbls Volume Progressed None											
Type of Relea	ase Oil &	Produced Wa	ater			Volume of Release 6-8 Bbls Volume Recovered None					
Source of Rel						Date and Hour of Occurrence Date and Hour of Discovery					
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required							Whom?				71111
By Whom?						Date and H	OUP		· · · · · · · · · · · · · · · · · · ·		
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.					
☐ Yes ☒ No							, , ,				
If a Watercourse was Impacted, Describe Fully.*											
FEB 2 4 2006											
99U-MITESIA											
Describe Cause of Problem and Remedial Action Taken.*											
Flowline leak due to corrosion approximately 30° of flowline replaced.											
approximately 50 of nowhile replaced.											
Describe Area Affected and Cleanup Action Taken.*											
Cellar and pit area of location. Cellar was dug out and material was tilled and blended with fertilizer.											
The second state of the second material was tilled and Diengly with Istilizer,											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
icaniations att	operators a	are required to	report and	d/or file certain re	elease n	iotifications an	d neriorm correct	tive actions for a	clascae which	mes en	donos-
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state,	or local law	s and/or regul	CD accept lations.	ance of a C-141 i	report d	loes not relieve	the operator of r	esponsibility for	compliance w	ith any	other
Signature: A. R. Small						OIL CONSERVATION DIVISION					
						TIM GUM					
						Approved by I	District Superviso	or:	DA W		B
Printed Name: J.B. Smith								·			
Title: Field Superintendent						Approval Date	: 3/7/06	Expiratio	n Date:		
E-mail Address:						Conditions of Approval:					
Date: 2/23/20 Attach Additi		s If Necessa	Phone:	505-365-8064				- н			