

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised June 10, 2003

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other REPAIR DOWNHOLE FAILURE	WELL API NO. 30-015-26304
	5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ConocoPhillips Company	6. State Oil & Gas Lease No. K-3271
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	7. Lease Name or Unit Agreement Name JAMES A
4. Well Location Unit Letter <u>H</u> : 1650 feet from the <u>NORTH</u> line and 660 feet from the <u>EAST</u> line Section <u>2</u> Township <u>22-S</u> Range <u>30-E</u> NMPM County <u>EDDY</u>	8. Well Number 8
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3220'; KB 3228'	9. OGRID Number 217817
	10. Pool name or Wildcat CABIN LAKE (DELAWARE)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: REPAIR DOWNHOLE FAILURE ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
SEE ATTACHED. REPAIR DOWNHOLE FAILURE

RECEIVED
MAR 08 2006
OCD-ARTESIA



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gay Thomas TITLE Regulatory Assistant DATE 03/02/2006
Type or print name Gay Thomas E-mail address: Gay.Thomas@conocophillips.com Telephone No. (432)368-1217

(This space for State use)

FOR RECORDS ONLY

APPROVED BY _____ TITLE _____ DATE MAR 13 2006
Conditions of approval, if any: _____



Daily summary

JAMES A 08

Job Type: REPAIR DOWNHOLE FAILURE

API/Bottom Hole UWI 300152630400	Field Name DISTRICT - CAPROCK SUB-DIS	Area MALJAMAR	County EDDY	State/Province NEW MEXICO	Operator ConocoPhillips	License No.
Original KB Elevation (ft) 3,228.00	Ground Elevation (ft) 3,220.00	KB-CF (ft) 3,228.00	KB-TH (ft) 3,228.00	Spud Date 4/16/1990	Rig Release Date 5/7/1990	

Start Date	Last 24hr Sum	Day Total	Cum Cost
8/29/2005 07:30	Arrive on location, held PJSA and scope of job meeting. Rig up. POOH w/rods and pump. All rods and bxs were good. Prepare to install BOP, pumped 20 bbls wtr to kill well. Noticed tbg leak under the slips and pits in tubing. Called for a 2 7/8" spear. Speared tubing and released TAC, layed down top jt and installed BOP. Prepared floor to scan tubing, shut down for day.		
8/30/2005 07:00	Held JSA and job scope. Blew down psi on casing. Rig up tuboscope and tally OOH. Scan 198 lts, abd 6 jts under TAC. Found 1st jt in slips with hole and jt #186 green, all rest were yellow/blue. Rig down Tuboscope. Rih with 6 jts 2 7/8" tbg, TAC, 198 jts 2 7/8" SN. Set TAC to 12 pts, and took off BOP. flange well back. Prepared to run rods, Shut down.		
8/31/2005 07:00	Held morning safety meeting. Bled well down. Pick up pump, RIH with Pump, 2- 1.5" K-bars, 2 - 3/4" guided rods, 258 7/8" Norris 97 rods, 4' of 7/8" subs and 1 - 1.5 x 26' x 7/8" polish rod. Hung well back on and load and test to 500#. Rig down and clean location.		