

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1529337640

OPERATOR

Initial Report Final Report

Name of Company	Burnett Oil Co., Inc	Contact	Leslie Garvis
Address	801 Chery Street, Ste 1500, Fort Worth, Texas 76102	Telephone No.	817-583-8730
Facility Name	Gissler A-2 Battery	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-33498 (GA 24)
---------------	-----	---------------	-----	---------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	14	17S	30E	1650	South	1650	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15 bbls	Volume Recovered	15 bbls
Source of Release	Oil Tank	Date and Hour of Occurrence	10/12/15	Date and Hour of Discovery	10/12/15 0900
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM - S. Tucker, OCD - H. Patterson via Email		
By Whom?	Leslie Garvis	Date and Hour	10/13/15 1806	5:00 PM	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 16 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
High level alarm malfunctioned on oil tank, communications failed to deliver message before oil reached top of tank. Alarm has been repaired.

Describe Area Affected and Cleanup Action Taken.*
All liquid was contained within the lined containment area. Liquids have been recovered and surface has been scraped..

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator	Approval Date: 10/20/15	Expiration Date: N/A
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 10/15/15	Phone: 817-583-8730	

* Attach Additional Sheets If Necessary

2RP. 3343