

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

DAB1529336845 OPERATOR Initial Report Final Report

Name of Company Burnett Oil Co., Inc	Contact Leslie Garvis
Address 801 Cherry Street, Ste 1500, Fort Worth, Texas 76102	Telephone No. 817-583-8730
Facility Name Gissler B 3-3	Facility Type Tank Battery
Surface Owner BLM	Mineral Owner BLM
API No. 30-015-41276 (GB 97)	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	17S	30E	441	South	467	West	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Water	Volume of Release 550 bbls	Volume Recovered 540 bbls
Source of Release Water Tank	Date and Hour of Occurrence 10/14/15	Date and Hour of Discovery 10/15/15 0900
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Phone Call and Email to BLM - S. Tucker, OCD - H. Patterson	
By Whom? Leslie Garvis	Date and Hour 10/15/15 1023	4:23 AM
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 16 2015
RECEIVED**

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Power failure at location caused the transfer pump to lose power and the high level alarm did not work. Alarm has been inspected and repaired.

Describe Area Affected and Cleanup Action Taken.*
Spill was contained within the firewall. Affected area is 60'x100'. All standing fluid has been picked up. Area will be assessed and remediated according to approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator	Approval Date: 10/20/15	Expiration Date: N/A
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval: <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 10/16/15 Phone: 817-583-8730	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/20/15

2RD-3342