

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1531427526

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Brett Fulks
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 432-301-3223
Facility Name Emerald PWU 20 62H	Facility Type New Well

Surface Owner State	Mineral Owner State	API No. 30-015-43372
---------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 20	Township 19S	Range 29E	Feet from the 1238	North/South Line FSL	Feet from the 248	East/West Line FWL	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	-------------------------	----------------------	-----------------------	----------------

Latitude: 32.6424438 Longitude: -104.1049327

NATURE OF RELEASE

Type of Release Spill Brine water	Volume of Release 15 BBL	Volume Recovered 14 BBL
Source of Release Drilling pit	Date and Hour of Occurrence 10/31/15 at 7:00 am	Date and Hour of Discovery 10/31/15 at 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour 11/02/15 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*

H2s alarms went off so the drilling crew evacuated the rig floor, leaving the pumps engaged. This resulted in the mud pits running over.

NM OIL CONSERVATION  
ARTESIA DISTRICT

NOV 09 2015

Describe Area Affected and Cleanup Action Taken.\*

Scraped contaminated 20 x 20 area and placed in cuttings bin. Will conduct sampling to confirm chloride levels.

RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron

Printed Name: Jeanette Barron

Title: Field Admin Support

E-mail Address: Jeanette.barron@dvn.com

Date: 11/06/15

Phone: 575.748.1813

Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Approval Date: 11/10/15

Expiration Date: N/A

Conditions of Approval:

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 12/12/15

2RP-3377