

Sent to NMOCD Dist 2 by
Devon via email 1/23/2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1532334246

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	Contact Kevin Phillips
Address PO Box 250 Artesia, NM 88211	Telephone No. 575-748-3371
Facility Name Todd 36 1	Facility Type SWD

Surface Owner State	Mineral Owner State	API No. 30-015-20341
---------------------	---------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter K	Section 36	Township 23S	Range 31E	Feet from the 1980	North/South Line WEST	Feet from the 1980	East/West Line NORTH	County EDDY
-------------------------	----------------------	------------------------	---------------------	------------------------------	---------------------------------	------------------------------	--------------------------------	-----------------------

Latitude: 32.2626871870239 Longitude: 103.733599857938

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 75 BBL	Volume Recovered 50 BBL
Source of Release Water tank leak	Date and Hour of Occurrence 1/21/15 2:00PM	Date and Hour of Discovery 1/21/15 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM- Jeff Robertson OCD- Mike Bratcher	
By Whom? Kevin Phillips	Date and Hour 1/22/15 10:15 PM BLM 1/22/15 1:00 PM OCD	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Hole in water tank.

Describe Area Affected and Cleanup Action Taken.*

Lease operator noticed a hole about 5' from the bottom of the tank. The containment was full and overflowing onto the location. 75 BBL total spill with 50 BBL recovered. Called SB Transportation for a vacuum truck to pick up water. Planning the cleanup with Enviro Clean.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jeanette Barron</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Jeanette Barron</u>	Signed By <u>Mike Bratcher</u>	
Title: <u>Field Admin Support</u>	Approved by Environmental Specialist:	
E-mail Address: <u>Jeanette.barron@dvn.com</u>	Approval Date: <u>11/19/15</u>	Expiration Date: <u>N/A</u>
Date: <u>1.23.15</u> Phone: <u>575-748-1813</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 12/19/15

2RP-3405