

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB1532751453		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <b>Devon Energy</b>		Contact <b>Aaron Kidd Construction Assistant Foreman</b>			
Address <b>PO Box 250 Artesia, NM 88211</b>		Telephone No. <b>575-513-1770</b>			
Facility Name <b>Ore Ida 14 Fed 2</b>		Facility Type <b>Oil</b>			
Surface Owner Federal		Mineral Owner Federal		API No. <b>30-015-28930</b>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>E</b>	<b>14</b>	<b>24S</b>	<b>29E</b>	<b>1980</b>	<b>N</b>	<b>330</b>	<b>W</b>	<b>EDDY</b>

Latitude: 32.219266 Longitude: -103.962202

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 25 BBL	Volume Recovered 20 BBL
Source of Release Produced water transfer line	Date and Hour of Occurrence 11/18/15 1:00 PM	Date and Hour of Discovery 11/18/15 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Jim Amos BLM Mike Bratcher	
By Whom? Aaron Kidd	Date and Hour OCD 11/19/15 7:30 AM BLM 11/19/15 7:45 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

**NOV 20 2015**

**RECEIVED**

If a Watercourse was Impacted, Describe Fully.\*N/A

Describe Cause of Problem and Remedial Action Taken.\*

While blading the lease road, the blade hit a 3" unmarked poly produced water transfer line. A berm was built to contain produced water until vacuum truck arrived. Shut down transfer pumps associated with transfer line.

Describe Area Affected and Cleanup Action Taken.\*

25 BBL of produced water was released on a 5 X 100 area on northeast side of lease road and 20 BBL was recovered. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jessica Sanchez</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <u>Jessica Sanchez</u>	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: <u>Field Admin Support</u>	Approval Date: <u>11/23/15</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Jessica.Sanchez@dvn.com</u>	Conditions of Approval:	
Date: <u>6.30.14</u> Phone: <u>575-746-5594</u>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: <u>12/23/15</u></b>	

Attached ☐

\* Attach Additional Sheets If Necessary

**2RP-3413**