

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535131213

6137

OPERATOR

Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Rudy Zuniga Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-390-5435
Facility Name Peridot 13 State 3H	Facility Type Oil
Surface Owner State	Mineral Owner State
API No 30-015-40778	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	12	19S	29E	1475	North	1245	East	Eddy

Latitude: N 32°67'78.95"

Longitude: W -104°02'38.22"

32.6782

NATURE OF RELEASE

104.02374

Type of Release Spill Produced water and oil	Volume of Release 1 bbl oil and 5 bbls produced water	Volume Recovered 1 bbl oil and 2 bbls produced water
Source of Release 1' tubing	Date and Hour of Occurrence 12.11.15 @ 12:00 pm	Date and Hour of Discovery 12.11.15 @ 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather @ OCD	
By Whom? Jesse Armendariz Assistant Production Foreman	Date and Hour 12.11.15 @ 12:55 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

NM OIL CONSERVATION
ARTESIA DISTRICT
DEC 16 2015
RECEIVED

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Gauging on 1' tubing blew out causing a 6 bbl oil and produced water release. Well was shut in to prevent further release. The gauge was replaced.

Describe Area Affected and Cleanup Action Taken.*

1 bbl oil and 5 bbl produced water was released on the North, Northwest of the facility. 1 bbl oil and 2 bbl produced water was recovered via vac truck. The affected area was 25"x35". All released fluid remained on the location. Environmental agency to be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Corina Moya</i>	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>12/17/15</i>	Expiration Date: <i>NA</i>
E-mail Address: corina.moya@dvn.com	Conditions of Approval:	
Date: 12.14.2015 Phone: 575.746.5559	Remediation per O.C.D. Rules & Guidelines	

PERMIT REMEDIATION PROPOSAL NO

Attached

LATER THAN: *1/17/16*

22P-3456

* Attach Additional Sheets If Necessary