

NM OIL CONSERVATION

ARTESIA DISTRICT

JAN 08 2016

Form C-141

Revised August 8, 2011

District I:
1625 N. French Dr., Hobbs, NM 88240
District II:
811 S. First St., Artesia, NM 88210
District III:
1000 Rio Brazos Road, Aztec, NM 87410
District IV:
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NA Billed 1156120

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company: COG Operating LLC <i>229137</i>		Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077	
Facility Name: COTTONWOOD 2 STATE SWD #001		Facility Type: SWD	
Surface Owner: State		Mineral Owner:	API No. 30-015-42356

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	2	26S	26E	400	South	1400	East	Eddy

Latitude 32.0656281 Longitude -104.2599487

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 25 bbls Oil ; 125 bbls PW	Volume Recovered: 25 bbls Oil ; 125 bbls PW
Source of Release: Nipple Fitting	Date and Hour of Occurrence: 12/9/2015 2:30 pm	Date and Hour of Discovery: 12/9/2015 2:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo DAVIS	Date and Hour: 12/11/2015 10:41 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a corroded nipple fitting on a pump. Vacuum trucks were dispatched to recover all standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a falcon lined facility. All fluid were able to be recovered and the equipment repaired. The facility was cleaned and put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>11/11/16</i>	Expiration Date: <i>NA</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: December 12, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

22P-3486