

# NM OIL CONSERVATION

ARTESIA DISTRICT

FEB 04 2016

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit to the appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Oxy Permian Ltd. 11/16/16 Contact Casey Summers  
Address 6 Desta Drive, Midland, TX 79705 Telephone No. (575) 513-8289  
Facility Name Harroun 15 #12 Facility Type Well location

Surface Owner Private-Henry McDonald Mineral Owner  API No. 30-015-32117

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	15	24S	29E					Eddy County, NM

Latitude N 32.21124° Longitude W 103.97459°

## NATURE OF RELEASE

Type of Release <u>Oil and produced water</u>	Volume of Release <u>3 bbls oil, 4 bbls produced water</u>	Volume Recovered <u>0 bbls</u>
Source of Release <u>Over-pressure of a 3" poly production line</u>	Date and Hour of Occurrence <u>01/20/2016</u>	Date and Hour of Discovery <u></u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <u>Mike Bratcher, Heather Patterson-NMOCD</u>	
By Whom? <u>Kathy Purvis @ BBC International</u>	Date and Hour <u>01/22/2016 @ 12:19 pm</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Over-pressure of a 3" poly production line caused 3 bbls of oil and 4 bbls of produced water to be spilled on to the ground. No fluids were recovered and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 40' x 60' both on and off location. Remediation will be completed in accordance with a remediation plan approved by NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>[Signature]</u>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <u>Casey Summers</u>	Signed By <u>[Signature]</u> Approved by Environmental Specialist:	
Title: <u>NM Environmental Advisor</u>	Approval Date: <u>2/5/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>Casey_Summers@oxy.com</u>	Conditions of Approval:	
Date: <u>2-4-16</u> Phone: <u>(575) 513-8289</u>	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>3/18/16</u>	

\* Attach Additional Sheets If Necessary

Attached ☐

2RP-3535