

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB16051654467* OPERATOR  Initial Report  Final Report

Name of Company	RKI E&P, LLC <i>246289</i>	Contact	Taylor Jones
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	539-573-7558
Facility Name:	Ross Draw Unit 42	Facility Type:	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42945
------------------------	------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	22	26S	30E	1980	FSL	1800	FWL	Eddy

Latitude: 32.02600 Longitude: -103.87139

**NATURE OF RELEASE**

Type of Release: Oil and Produced Water	Volume of Release: 13 Bbbls	Volume Recovered: 11 Bbbls
Source of Release: Polish rod Liner	Date and Hour of Occurrence: 2/20/16 - 10:00 MT	Date and Hour of Discovery: 2/20/16 - 10:00 MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? <b>NM OIL CONSERVATION</b>	
By Whom?	Date and Hour:	ARTESIA DISTRICT
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A

**RECEIVED**

Describe Cause of Problem and Remedial Action Taken.\*  
Polish Rod liner became loose, allowing the release of crude oil and produced water. Crew shut well in and tightened the liner.

Describe Area Affected and Cleanup Action Taken.\*  
All fluids remained on well site. Vacuum truck dispatched to recover all free standing fluids. Affected soil on well pad to be dug and hauled to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Taylor Jones</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Safety Specialist II	Approval Date: 2/25/16	Expiration Date: N/A
E-mail Address: taylor.jones@wpenergy.com	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b>	
Date: 02/22/16 Phone: 539-573-7558	Attached <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 3/26/16

*2RD-3564*