

MAR 08 2006

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210-2118
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

March 7, 2006

Mike Bratcher
District 2, NM Oil Conservation Division
1301 W. Grand St.
Artesia NM 88210

RECEIVED
MAR 07 2006
GOB-ARTESIA

#3
RE: Yates Federal Battery, API # 30-015-22116

Mr. Bratcher:

Attached please find a C-14~~4~~ for the removal of the below grade fiberglass tank at the Yates Federal Battery.

This tank was tested April 29, 2005, and witnessed by Yates production foreman Gene Poteet, attached is a copy of that test.

A print out from the State Engineers Office to indicate water is included.

The remediation plan due in your office on March 15, 2005 is being reformulated and will be submitted prior to, or on that date.

Yates has made the required One-Call, and is ready to remove the tank, we will notify you 24hrs before removal to give you the opportunity to witness the work.

Any Questions, please contact me or Jerry Fanning at 748-1471.

Sincerely;

Dan Dolan
Environmental Regulatory Agent

New Mexico Office of the State Engineer
POD Reports and Downloads

Township: 18S Range: 25E Sections:

NAD27 X: Y: Zone: Search Radius:

County: Basin: Number: Suffix:

Owner Name: (First) (Last) ☐ Non-Domestic ☐ Domestic
☒ All

POD / Surface Data Report

Avg Depth to Water Report

Water Column Report

Clear Form

iWATERS Menu

Help

AVERAGE DEPTH OF WATER REPORT 03/07/2006

(Depth Water in Feet)

Bsn	Tws	Rng	Sec	Zone	X	Y	Wells	Min	Max	Avg
RA	18S	25E	01				3	170	187	176
RA	18S	25E	02				1	175	175	175
RA	18S	25E	03				4	140	185	173
RA	18S	25E	04				2	155	155	155
RA	18S	25E	10				1	168	168	168
RA	18S	25E	12				1	200	200	200
RA	18S	25E	18				1	230	230	230
RA	18S	25E	21				2	150	220	185
RA	18S	25E	24				1	158	158	158
RA	18S	25E	26				1	200	200	200
RA	18S	25E	32				1	300	300	300
RA	18S	25E	36				1	270	270	270


Record Count: 19

Below Grade Tanks

Location or battery name	Size tank or earth pit	Is it Fiberglass earth steel	Leak Detection Yes/No	Section	Township	Range	Footages	Date Last Tested (Annual Required)	Name of the OCD inspector that was contacted	Foreman
Achen Frey DM Batt.	150 BBLs	Fiberglass	Yes	14	17S	25E	NE 1/4 SE 1/4	Tank Removed	N/A	SM
Allison CQ Fed 9	210 BBLs	Fiberglass	Yes	26	19S	24E	660 FSL			GP
Babcock IR	210 BBLs	Fiberglass	Yes	26	18S	25E	405 FSL			GP
Boykin ACV	210 BBLs	Fiberglass	Yes	34	18S	26E	NW 1/4 NW 1/4			WB
Burton Flats SWD	40 BBLs	Fiberglass	No	21	20S	29E	1980FNL		4/26/2005	DM
Cannon FW	210 BBLs	Fiberglass	Yes	21	18S	26E	Unit C			WB
Cleveland	210 BBLs	Fiberglass	Yes	33	18S	26E	NW 1/4 NE 1/4			WB
Dagger Draw 19SW #4	20 BBLs	Steel	No	19	19S	25E	1980 FSL			GP
Dayton EX	210 BBLs	Fiberglass	Yes	21	18S	26E	Unit K			WB
Dayton FI	210 BBLs	Fiberglass	Yes	28	18S	26E	Unit A			WB
Dee 36SW State #2	20 BBLs	Steel	No	36	19S	24E	940 FSL			GP
Deeter ADV	210 BBLs	Fiberglass	Yes	27	18S	26E	560 FSL			WB
EADS GA	210 BBLs	Fiberglass	Yes	22	18S	26E	Unit N			WB
Eagle Creek BL Batt.	150 BBLs	Fiberglass	Yes	23	17S	25E	SE 1/4 SW 1/4			SM
Fed AK	210 BBLs	Fiberglass	Yes	3	19S	25E				GP
Fed AY	210 BBLs	Fiberglass	Yes	25	18S	25E	2310 FNL	1980 FNL	4/29/2005	GP
Federal BQ Batt.	150 BBLs	Fiberglass	Yes	27	17S	25E	NE 1/4 NW 1/4		Van Barton 4/27/05	SM
Federal BW Batt.	150 BBLs	Fiberglass	Yes	22	17S	25E	SE 1/4 SE 1/4			SM
Federal BX Batt.	150 BBLs	Fiberglass	Yes	27	17S	25E	SW 1/4 NE 1/4			SM
Federal BZ Batt.	150 BBLs	Fiberglass	Yes	21	17S	25E	SE 1/4 SE 1/4			SM
Federal CD Batt.	150 BBLs	Fiberglass	Yes	28	17S	25E	NE 1/4 NW 1/4			SM
Federal LDY Batt.	150 BBLs	Fiberglass	Yes	27	17S	25E	SE 1/4 NW 1/4			SM
Federale BO Batt.	150 BBLs	Fiberglass	Yes	23	17S	25E	NW 1/4 NW 1/4	Tank Removed	N/A	WB
Flint GU	210 BBLs	Fiberglass	Yes	22	18S	26E	NW	SE		WB
Gates AAC	210 BBLs	Fiberglass	Yes	22	18S	26E	NE 1/4 NW 1/4			WB
Gerard AW	210 BBLs	Fiberglass	Yes	25	18S	25E	990 FSL	1650 FEL	4/29/2005	GP
Gissler AV Batt.	150 BBLs	Fiberglass	Yes	23	17S	25E	SE 1/4 NW 1/4	Tank Removed	N/A	SM
Gissler AVB Batt.	150 BBLs	Fiberglass	Yes	23	17S	25E	SE 1/4 NW 1/4	Tank Removed	N/A	SM
Gushwa DR	210 BBLs	Fiberglass	Yes	35	18S	25E	1980 FNL	660 FNL		WB
Hoffman PL	210 BBLs	Fiberglass	Yes	27	18S	26E	NW 1/4 SW 1/4			WB
Hornbaker	210	Fiberglass							4/29/2005	GP
Ingram Jackson BV Batt.	150 BBLs	Fiberglass	Yes	27	17S	25E	NE 1/4 NE 1/4		Van Barton 4/27/05	SM
J Lazy J Batt.	150 BBLs	Fiberglass	Yes	22	17S	25E	SE 1/4 NE 1/4			SM
Jackson AT Batt.	150 BBLs	Fiberglass	Yes	14	17S	25E	SW 1/4 SE 1/4	Tank Removed	N/A	SM
Jackson Estate BY Batt.	150 BBLs	Fiberglass	Yes	22	17S	25E	NE 1/4 SW 1/4	Tank Removed	N/A	SM
Kincaid BI	210	Fiberglass							5/2/2005	GP
Kiwi AKX St. #8	20 BBLs	Fiberglass	No	16	22S	32E				JC
Lawrence ADZ	210 BBLs	Fiberglass	Yes	22	18S	26E	SE 1/4 NE 1/4			WB
Lincoln PC	210 BBLs	Fiberglass	Yes	33	18S	25E	2310 FNL	990 FNL		GP
Linda SWD (Federal HJ)	20 BBLs	Fiberglass	No	31	6S	26E	330' FNL	330' FEL	Tank Removed	PH
Lodewick A #1	20 BBLs	Steel	No	19	19S	25E	660 FNL	1980 FNL		GP
McCaw BT Batt.	150 BBLs	Fiberglass	Yes	15	17S	25E	SW 1/4 NE 1/4	Tank Removed	N/A	SM
Mimosa AHS Fed. #1	100 BBLs	Fiberglass	Yes	4	20S	24E	1980 FSL	810 FEL	5/2/2005	GP
Mitchell IN Batt.	150 BBLs	Fiberglass	Yes	23	17S	25E	NW 1/4 SE 1/4			SM
Mobil CI	210 BBLs	Fiberglass	Yes	6	19S	25E	1980 FSL	1980 FEL	5/2/2005	GP
Mojave Water Transfer	30 BBLs	Fiberglass	No	35	20.5S	23E	990 FNL	660 FEL		WB
Monosanto Foster SWD #1	20 BBLs	Steel	No	5	20S	25E	660 FNL	660 FNL	5/2/2005	GP

Location or battery name	Size tank or earth pit	Is it Fiberglass earth steel	Leak Detection Yes/No	Section	Township	Range	Footages		Date Last Tested (Annual Required)	Name of the OCD inspector that was contacted	Foreman
Morris Estate CC Batt.	150 BBLs	Fiberglass	Yes	14	17S	25E	SW 1/4	SW 1/4	Tank Removed	N/A	SM
Nicholas BJ	210 BBLs	Fiberglass	Yes	5	19S	25E	2310 FSL	2310 FEL			GP
Nickson BM	210 BBLs	Fiberglass	Yes	30	18S	26E	330 FNL	330 FEL	4/29/2005	Van Barton 4/27/05	GP
Nix Curtis BH	210 BBLs	Fiberglass	Yes	25	18S	25E	2310 FSL	330 FEL	4/29/2005	Van Barton 4/27/05	GP
Nix Curtis JF	210 BBLs	Fiberglass	Yes	25	18S	26E		Unit A	4/29/2005	Van Barton 4/27/05	GP
Nix PK	210 BBLs	Fiberglass	Yes	27	18S	26E	SW 1/4	NE 1/4			WB
Olsen MY	210 BBLs	Fiberglass	Yes	33	18S	26E	NE 1/4	SE 1/4			WB
Riverside ASS #1	20 BBLs	Fiberglass	No	8	17S	27E	1650 FSL	660 FEL			DM
Routh RU Com #2	100 BBLs	Fiberglass	Yes	14	19S	24E	660' FNL	1980' FEL	5/2/2005	Van Barton 4/27/05	GP
Roy AET SWD #3	100 BBLs	Fiberglass	Yes	7	19S	25E	810' FSL	660' FEL	5/2/2005	Van Barton 4/27/05	GP
Sawbuck Water Transfer	210 BBLs	Fiberglass	Yes	23	20S	24E	1650 FNL	1790 FEL			WB
Scout EH Fed #1	210 BBLs	Fiberglass	Yes	34	18S	25E	2310 FNL	1650 FEL			GP
Stark BG	210 BBLs	Fiberglass	Yes	25	18S	25E	660 FNL	2310 FWL	4/29/2005	Van Barton 4/27/05	GP
State CO SWD	100 BBLs	Fiberglass	Yes	36	19S	24E	1980 FSL	1980 FWL	5/2/2005	Van Barton 4/27/05	GP
State D SWD	20BBLs	Fiberglass	No	16	20S	24E					WB
Waldrip JY	210 BBLs	Fiberglass	Yes	34	18S	26E	NW 1/4	SW 1/4			WB
White IU	210 BBLs	Fiberglass	Yes	28	18S	26E	NE 1/4	SE 1/4			WB
Wilkinson AZ	210 BBLs	Fiberglass	Yes	25	18S	25E	990 FSL	2310 FWL	4/29/2005	Van Barton 4/27/05	GP
Winter DN Batt.	150 BBLs	Fiberglass	Yes	14	17S	25E	SE 1/4	SE 1/4			SM
Yates AS Fee	210 BBLs	Fiberglass	Yes	25	18S	25E	2310 FSL	2310 FWL	4/29/2005	Van Barton 4/27/05	GP
Yates Fed	210 BBLs	Fiberglass	Yes	26	18S	25E	2310 FNL	150 FEL	4/29/2005	Van Barton 4/27/05	GP

Note: The tank integrity must be tested annually.



[Dayton; NM] Scale: 1" = 0.379Mi 610Mt 2,000Ft, 1 Mi = 2.640" , 1 cm = 240Mt