

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **NM OIL CONSERVATION**  
Energy Minerals and Natural Resources ARTESIA DISTRICT  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

MAY 05 2016

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

NAB1013041771

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company	XTO Energy, Inc. <u>5380</u>	Contact	John Robinson
Address	500 W. Illinois, Suite 100, Midland, TX 79701	Telephone No.	575-441-5199
Facility Name	Golden Child state 6 - 1H	Facility Type	well
Surface Owner	Mineral Owner	API No.	30-015-43003

**LOCATION OF RELEASE**

Unit Letter	Section 6	Township 25 S	Range 29 E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	--------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Oil and Produced Water	Volume of Release	10.10 Oil and 90.90 Produced Water	Volume Recovered	10 Oil and 90 Produced Water
Source of Release		Date and Hour of Occurrence	5-3-16 8:00 am	Date and Hour of Discovery	5-3-16 10:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Heather Patterson. Voice message		
By Whom?	John Robinson	Date and Hour	5-3-16 11:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Flow line washed out and leaked 101 bbls of fluid on location. Pumper shut in well and called a vacuum truck to clean up all the fluid.

Describe Area Affected and Cleanup Action Taken.\*

Leak stayed on well pad and we will dig out contaminated soil and replace with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: <u>John Robinson</u>	Approved by Environmental Specialist: <u>[Signature]</u>
Printed Name: John Robinson	Approval Date: <u>5/6/16</u> Expiration Date: <u>N/A</u>
Title: Maintenance Foreman	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>
E-mail Address: john_robinson@xtoenergy.com	<b>SUBMIT REMEDIATION PROPOSAL NO</b>
Date: 5-5-16 Phone: 575-441-5199	<b>LATER THAN: <u>5/9/16</u></b>

\* Attach Additional Sheets If Necessary

2RP-3677