

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION
ARTESIA DISTRICT

MAY 16 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1613743288

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>11/01/10</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Riverbend Federal #8 SWD Battery	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-28390
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	23	24S	29E					Eddy County, NM

Latitude N 32.20882° Longitude W 103.96275°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	200 bbls	Volume Recovered	180 bbls
Source of Release	Faulty nipple on the triplex pump	Date and Hour of Occurrence	05/05/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	05/05/2016 @ 2:53 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
A faulty nipple on the triplex pump caused 200 bbls of produced water to leak onto location. A vacuum truck recovered 180 bbls of produced water and the nipple was replaced.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 90' x 150' on location about 3 feet from the triplex pump. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Casey Summers	Signed By <i>Mike Bratcher</i>	
Title:	NM Environmental Advisor	Approved by Environmental Specialist:	
E-mail Address:	Casey.Summers@oxy.com	Approval Date:	5/16/16
Date:	5-16-16	Expiration Date:	N/A
Phone:	(575) 513-8289	Conditions of Approval:	Attached <input type="checkbox"/>
		Remediation per O.C.D. Rules & Guidelines	
		SUBMIT REMEDIATION PROPOSAL NO	
		LATER THAN: <u>5/16/16</u>	

* Attach Additional Sheets If Necessary

2RP-3694