District 1 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Date: 06-20-2016

* Attach Additional Sheets If Necessary

Phone: 432-683-7443

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141 Revised August 8, 2011

JUN 2 0 2016 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

SUBMIT REMEDIATION PROPOSAL NO ARP-3747

Release Notification and Corrective Action												
AAAAA						OPERATOR						
Name of Co		Contact:			Robert McNeill							
Address:	600 Wes	Telephone No. 432-683-7443										
Facility Nan	ne:	Facility Type: Tank Battery										
Surface Owner: State Mineral Owner:						API No. 30-015-34438					15-34438	
Unit Letter Section Township Range Feet from the North/South Line Feet from the Enst/West Line County												
Unit Letter	Section	Township	Range	Feet from the		South Line	East/West Line		County			
D	D 16 23S 29E 319					North 946			West Eddy			
Latitude 32.3115883 Longitudes 103.9951782 NATURE OF RELEASE												
Type of Release:										olume Recovered:		
Produced Water						17BBLS Of Produced Water			16BBLS Of Produced Water			
Source of Release: Heater Treater						Date and Hour of Occurrence: 06-17-2016 1:00pm			Date and Hour of Discovery: 06-17-2016 1:00pm			
Was Immediate Notice Given?						If YES, To Whom?			00-17-2010 1.00ри			
<u>_</u>			Yes 🗵	No 🖾 Not Re	equired			_				
By Whom?						Date and Hour:						
Was a Watercourse Reached? ☐ Yes ☐ No						If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*												
Describe Cause of Problem and Remedial Action Taken.*												
Describe Cause of Problem and Action Taken,												
A fitting on the bottom of the heater treater failed due to corrosion, replaced the fitting with a new one.												
Describe Area Affected and Cleanup Action Taken.*												
Th	lauter a Catal	1			77 ! .	0	F.E.I. V. 201 i G		L			
				n a lined facility. ncho will have the								
				plan to the NMC								
					· .							
				is true and comp d/or file certain t								
				e of a C-141 repo								
				investigate and r								
or the enviror federal, state,				tance of a C-141	report d	oes not reliev	e the operator of	respons	ibility for co	mpliance w	vith any other	SE.
reactor, state,	Of TOCES IN		_	,	- 		OIL CON	SERV	ATION	DIVISIO	MC	
Signature:		Zal	<u> + 1/2</u>	/			<u>010 0011</u>	<u> </u>	17	. /	チ	
Printed Name: Robert Grubbs Jr.						Approved by Environmental Specialist:						
Title		enior Environ	mantal C-	ardinator			LANDIL		t i	Date: K)//	4	
Title:						Approval Dat		<u> </u>	Expiration I	Jare: 14/	4	
E-mail Addre	ess:	rgrubbs@	concho.co	m		Conditions of	Approval:			Attached		
Date: 06.20	2016	Dhone	. 412 601	7443	Remediation per O.C.D. Rules & Guidelines							

..ATER THAN:_