## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

**David Martin** 

Cabinet Secretary

David Catanach, Director Oil Conservation Division



**Tony Delfin** 

**Deputy Cabinet Secretary** 

## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

30-Jun-16

## LARRY MARKER DBA MARKER OIL

PO BOX 3188

Roswell NM 88202-8202

Comments on Inspection:

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

NORTH SQUARE LAKE UNIT No.011				O-19-16S-31E	30-015-04857-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
06/30/2016	Routine/Periodic	Tony Morales	Yes	No	10/3/2016	iTM1618246478
	Violations					
	Absent Well Identification Signs (R	tule 103)				
	General Housekeeping (Rule 114)					
	General Housekeeping (Rule 114)					
Comments of	on Inspection: OK. All Equipr	ment and Location in IGN NOT VISIBLE.		. PJ. STAINING AR	OUND WELL HEAD	
	on Inspection: OK. All Equipr	GN NOT VISIBLE.		. PJ. STAINING AR A-30-16S-31E	OUND WELL HEAD	
	on Inspection: OK. All Equipm LOCATION SI	GN NOT VISIBLE.				
NORTH SQ Inspection Date	OK. All Equipm LOCATION SI DUARE LAKE UNIT No.199	GN NOT VISIBLE.		A-30-16S-31E *Significant	30-015-33068-00-0 Corrective	00
NORTH SQ Inspection	OK. All Equipmed LOCATION SINUARE LAKE UNIT No.199  Type Inspection	IGN NOT VISIBLE. Inspector	Violation?	A-30-16S-31E *Significant Non-Compliance?	30-015-33068-00-0 Corrective Action Due By:	Inspection No.

OK. All Equipment and Location in Good Shape. PJ. OLD TUBING ON LOCATION.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Offic

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.