

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

AUG 11 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1622536318 OPERATOR Initial Report Final Report

Name of Company	Oxy Permian Ltd. <u>16696</u>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	TDC 8 State #001	Facility Type	Well
Surface Owner	State	Mineral Owner	API No. 30-015-32898

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	8	19S	29E					Eddy

Latitude N 32.67265° Longitude W 104.10448°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	7 bbls	Volume Recovered	0 bbls
Source of Release	Internal corrosion of a 2.875" steel disposal line	Date and Hour of Occurrence	07/30/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/01/2016 @ 12:36 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Internal corrosion of a 2.875" steel disposal line caused a leak of 7 bbls of produced water. No fluids were recovered and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*
The affected area is approximately 100' x 65' on location around the well head. Remediation will be completed in accordance with an approved remediation plan from NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	8/12/16
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	N/A
Date:	8-11-16	Phone:	(575) 513-8289
		Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 9/12/16

ARP 3825

* Attach Additional Sheets If Necessary