

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

AUG 22 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB11623634146

OPERATOR

Initial Report Final Report

Name of Company	Oxy Permian Ltd. <i>1166916</i>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Goodnight 27-4 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-39142

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	27	23S	29E					Eddy County, NM

Latitude N 32.26961° Longitude W 103.97466°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	7 bbls including rain water	Volume Recovered	7 bbls
Source of Release	Compromised Tee on water line	Date and Hour of Occurrence	08/19/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A compromised tee on the water line caused 7 bbls of produced water to leak. A vacuum truck recovered all free-standing fluids and the line was returned to service.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 25' x 15' with all of the leak staying inside the lined containment. Remediation was completed by removing the free-standing fluids and all other affected materials.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

OIL CONSERVATION DIVISION

Signature:		Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name:	Casey Summers	Approval Date:	8/23/16
Title:	NM Environmental Advisor	Expiration Date:	NIA
E-mail Address:	Casey_Summers@oxv.com	Conditions of Approval:	FINAL
Date:	8-22-16	Phone:	(575) 513-8289
		Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3841