

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 07 2016

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

DAB1625332986

OPERATOR

Initial Report Final Report

Name of Company: XTO Energy, Inc.	Contact: Dudley McMin
Address: 500 W. Illinois Ave., Suite 100, Midland, TX 70701	Telephone No.: (432) 682-8873
Facility Name: Nash Draw Unit Battery #9	Facility Type: Tank Battery (Equipment Removed)
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-26991	

LOCATION OF RELEASE

Unit Letter B	Section 13	Township 23S	Range 29E	Feet from the 860	North/South Line North	Feet from the 2210	East/West Line East	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------

Latitude 32.309722 Longitude -103.936944

NATURE OF RELEASE

Type of Release: Crude Oil/Produced Water	Volume of Release: Unknown	Volume Recovered: None
Source of Release: Spills	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 07-20-2016
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Hydrocarbons and chloride in soil due to historic use of tank battery reported in soil samples by laboratory following removal of tanks and equipment. Will remediate to OCD and BLM requirements.		
Describe Area Affected and Cleanup Action Taken.* Affected soil to be excavated, treated onsite treatment or disposed offsite at OCD approved facility. Refer to attached analytical data summary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>Luke Williams</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Luke Williams	Approval Date: <i>9/8/16</i>	Expiration Date: <i>N/A</i>
Title: EH&S Coordinator	Conditions of Approval: <input type="checkbox"/> Remediation per O.C.D. Rules & Guidelines	
E-mail Address: Luke.Williams@xtoenergy.com	SUBMIT REMEDIATION PROPOSAL NO	
Date: 09-07-2016 Phone: (432) 683-8873	LATER THAN: <u>10/1/16</u> 2RD-3876	

* Attach Additional Sheets If Necessary