

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 07 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1625241913

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: BUCKSHOT STATE COM #003H	Facility Type: Tank Battery
Surface Owner: State	Mineral Owner:
API No. 30-015-41094	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	31	24S	28E	100'	South	1700'	West	Eddy

Latitude 32.1668892 Longitude 104.1299591

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 245bbbs	Volume Recovered: 243bbbs
Source of Release: Valve	Date and Hour of Occurrence: 09-05-2016 1:55 pm	Date and Hour of Discovery: 09-05-2016 1:55 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Amber Grover - SLO	
By Whom? Robert Grubbs Jr	Date and Hour: Tue 9/6/2016 11:25 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* The release was caused by a valve being in the wrong position. Placed the valve in the correct position.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: <i>[Signature]</i>	SIGNED BY <i>[Signature]</i>	
Printed Name: Robert Grubbs Jr	Approved by Environmental Specialist	
Title: Senior Environmental Coordinator	Approval Date: <i>9/8/16</i>	Expiration Date: <i>NIA</i>
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: September 7, 2016 Phone: 432-683-7443	SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <i>10/9/16</i>	

* Attach Additional Sheets If Necessary

2RP-3868