

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 27 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC **Contact:** Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701 **Telephone No.** 432-683-7443
Facility Name: DUMP YARD 2 STATE #002H **Facility Type:** Tank Battery

Surface Owner: State **Mineral Owner:** **API No.** 30-015-42518

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	02	21S	28E	190'	South	1700'	West	Eddy

Latitude 32.5025635 Longitude 104.0603485

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 23bbbls	Volume Recovered: 22bbbls
Source of Release: Steel flowline	Date and Hour of Occurrence: 09-25-2016 12:00pm	Date and Hour of Discovery: 09-25-2016 12:00pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Corroded steel flowline due to age. Replace bad section of pipe with a new section of pipe.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 9/27/16	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 27, 2016 Phone: 432-683-7443	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/27/16

2RP-3913