

CDistrict I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION
ARTESIA DISTRICT

SEP 28 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1627451148 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <u>2140737</u>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit 17 Battery	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-27784	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	6	23S	31E	1970	North	1930	West	Eddy

Latitude 32.235007° Longitude -103.819183°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	22 bbls	Volume Recovered	15 bbls
Source of Release	Heater Treater water line	Date and Hour of Occurrence	9/19/2016 time unknown	Date and Hour of Discovery	9/19/2016 approx. 9 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	N/A		
By Whom?	N/A	Date and Hour	N/A		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Buried water dump line from heater treater to produced water tank developed hole due to corrosion. Line was isolated and clamped until repairs can be made.

Describe Area Affected and Cleanup Action Taken.*
The leak affected approximately 50 square feet of pasture west of the battery location and 2,600 square feet of caliche pad on location. Standing fluids were removed and impacted surface soils have been scraped and removed to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>[Signature]</u>		OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth		Approved by Environmental Specialist <u>[Signature]</u>	
Title: EHS Remediation Specialist		Approval Date: <u>9/29/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: ACRuth@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 9/28/2016 Phone: 432-661-0571		SUBMIT REMEDIATION PROPOSAL NO <u>114116</u>	

* Attach Additional Sheets If Necessary

LATER THAN: 114116

2RP-3919