

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION  
ARTESIA DISTRICT

OCT 19 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**NAB 1629855846** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294, Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Goodnight 27 Federal #002H *	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-43809

LOCATION OF RELEASE

**\* 30-015-34137**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	27	23S	29E					Eddy County, NM

Latitude N 32.27536° Longitude W 103.97690°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	5 bbls oil, 5 bbls produced water	Volume Recovered	10 bbls
Source of Release	Faulty valve on the well head	Date and Hour of Occurrence	10/12/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@ BBC International, Inc.	Date and Hour	10/13/2016 @ 11:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A faulty valve on the well head caused 5 bbls of oil and 5 bbls of produced water to leak onto the ground. A vacuum truck recovered 10 bbls of fluids and the valve was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 125'x 100' on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Casey Summers		Approved by Environmental Specialist: 	
Title: NM Environmental Advisor		Approval Date: 10/24/16	Expiration Date: N/A
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 10-19-16 Phone: (575) 513-8289		<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: 11/21/16

2RP-3948