

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

FEB 22 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1705527752

6137

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Danny Velo, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-703-3360
Facility Name	Serene Sisters 25 Fed 1H	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No	30-015-38314
---------------	---------	---------------	---------	--------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	25	18S	31E	254	FNL	953	FEL	Eddy

Latitude: 32.7251549

Longitude: -103.8175125

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	80bbbls	Volume Recovered	80bbbls
Source of Release	Oil tank	Date and Hour of Occurrence	February 18, 2017 @ 9:30 AM	Date and Hour of Discovery	February 18, 2017 @ 9:30 AM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Shelly Tucker, BLM Mike Bratcher, OCD		
By Whom?	Jesse Armendariz, Asst. Production Foreman	Date and Hour	Shelly Tucker, BLM February 20, 2017 @ 8:26 AM Mike Bratcher, OCD February 20, 2017 @ 8:29 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Due to corrosion on the bottom of an oil tank a hole developed. The oil in the tank was immediately transferred to a different tank in the battery to stop the release. The tank has been taken out of service until repairs can be made.

Describe Area Affected and Cleanup Action Taken.* Approximately 80bbbls of oil was released in to lined containment. A vacuum truck was dispatched and recovered all 80bbbls from the lined containment. The liner was checked for holes and none were found. No further action is necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <u>Mike Bratcher</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.fisher@dmv.com	Approval Date: 2/24/17	Expiration Date: N/A
Date: 2/21/17 Phone: 575.748.1829	Conditions of Approval: Containment Cleaned Liner inspected	
	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-4125