

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 21 2018

Form C-141
Revised April 3, 2017

Oil Conservation Division DISTRICT II-ARTESIA CO. CD
1220 South St. Francis Dr.
Santa Fe, NM 87505
On the appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: XTO Energy 5380	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Corral Canyon Federal Com #029H	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No: 30-015-44641
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 4	Township 25S	Range 29E	Feet from the 180	North/South Line South	Feet from the 196	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.152636 Longitude -103.997776 NAD83

NATURE OF RELEASE



Type of Release Fresh water and approximately 1 gallon of biocide	Volume of Release 40 BBL water, approximately 1 gallon of biocide	Volume Recovered 40 BBL water, approximately 1 gallon of biocide
Source of Release Pump	Date and Hour of Occurrence 5/6/2018, AM	Date and Hour of Discovery 5/6/2018, AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Crystal Weaver (NMOCD) Shelly Tucker and Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour: 5/7/2018, 7:40 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
During water transfer job, operator did not hear radio command to close valve. This caused 40bbl of fluid to release into impervious lined containment. Valves were shut properly and vacuum truck dispatched.

Describe Area Affected and Cleanup Action Taken.*
The release affected the area within impervious lined containment. All fluids were recovered from the containment by vacuum truck. A SH&E Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified there was no visual evidence of a liner breach.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 5/22/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval: FINAL	Attached: <input checked="" type="checkbox"/> 2 PP-4761
Date: 5/21/2018 Phone: 432-221-7331		

* Attach Additional Sheets If Necessary