Submit I Copy To Appropriate District Office	State of New Mexico		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources		Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District 11 – (575) 748-1283			WELL API NO.
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-26623
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	,		K-6385
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Dee 36 SE State	
PROPOSALS.)		8. Well Number	
		3	
2. Name of Operator	AKTEOIA DIOTINO		9. OGRID Number
EOG Y Resources, Inc. 3. Address of Operator	SEP 0 5 2018		025575 10. Pool name or Wildcat
104 South Fourth Street, Artesia, 1			N. Seven Rivers; Glorieta-Yeso
		N. Seven Rivers, Giorieta- 1 eso	
4. Well Location RECEIVED			
Unit Letter J : 1650 feet from the South line and 1980 feet from the East line			
Section 36 Township 19S Range 24E NMPM Eddy County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3603' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK			
TEMPORARILY ABANDON] CHANGE PLANS ☐ COMMENCE DRIL		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB
DOWNHOLE COMMINGLE	ļ		
CLOSED-LOOP SYSTEM			
OTHER:			to pressure monitor well
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
RESUBMIT			
2/9/18 – MIRU. Pumped 40 bbls 10# brine down tubing and 90 bbls down casing. POOH with production equipment. Pumped 30 bbls fresh water down casing. NU BOP. 2/10/18 – RJH to CIBP at 7524'. Broke circulation with 170 bbls fresh water, pumped another 60 bbls. Spotted 25 sx Class "H" cement on top of CIBP. Approximate TOC at 7393'. As per Gilbert Cordero with NMOCD do not have to tag. Set a 7" CIBP at 6350'. Pumped 2% KCL water and 90 bbls. Broke circulation. Pumped 200 bbls. Tested casing to 1000 psi, good. Spotted 25 sx Class "C" cement on top of CIBP. Displaced with 35.8 bbls. 2/11/18-2/13/18 - Tagged TOC at 6250'. Ran GR/CCL log from 3400' up to surface with 1000 psi. Perforated Yeso 3274'-3302' (29). Tested casing to 500 psi, good. Acidized with 5000g 20% NEFE acid. Swab tested. 2/15/18-2/16/18 - Loaded 18 bbls of 2% KCL water. Loaded casing with 2% KCL. Perforated Yeso 3155'-3190' (36). Acidized with 5000g 20% HCL acid.			
2/18/18-2/20/18 - Perforated Yeso 2908'-2940' (33). Acidized with 2000g 7-1/2% HCL acid. 2/23/18 - Set a 7" CIBP at 2958'. Pumped 35' cement on top of CIBP. Approximate TOC at 2923'. 2/23/18 - Ran Radial Cement Bond/GR/CCL log up to 1500'. Tagged TOC at 2931'. Loaded casing with 65 bbls 2% KCL. Tested to 2000 psi, good. 2/24/18 - Ran 2-7/8" tubing with perforating gun at 2373'-2393' and pressure gauge at 2368'. Packer to isolate at 2363'. Perforating gun at 2210'-2214' and gauge at 2205'. Fired perforating guns and began monitoring pressure.			
Spud Date:	Rig Release Da	te:	
11-2-2018 - TA for Dressure Month Status well supper 2-34-2019. I hereby certify that the information above is true and complete to the best of my knowledge and belief. See a Hack must by			
SIGNATURE			
Type or print name Tina Huerta E-mail address: tina_huerta@eogresources.com PHONE: _575-748-4168_			
APPROVED BY: DATE 9-7-18			
APPROVED BY: DATE 7-7-18 Conditions of Approval (if any):			

Dee State #3 Actual Casing A 9-5/8" K-55 36# 1201 Casing B 7" K-55 26# 8109 Pressure gauges **Perforations** Monitor 2210 2214 Monitor 2373 2393 TOC 2931 2908 CIBP Perf and swab - open for monitoring 2931 2958 Perf and swab - plugged back 2940 2931 33 holes 3155 Perf and swab - plugged back 3190 36 holes Perf and swab - plugged back 3274 3302 - L 29 holes TOC 6250 CIBP 6350 6450 6500 Inactive 7393 TOC 7524 7530 - 12/8/2603 CIBP Inactive 7594 7804 7902 7964 Inactive

.

DEE OQ STATE #3

EOG-Y RESOURCES Section 36-T19S-R24E 30-015-26623

11-2-2018 – TA Status for Pressure Monitor well will expire on 2-24-2019. NOTE: Pressure monitoring began on 2-24-2018.

NOTE: Before an extension will be granted for TA status for this pressure monitor well, all results from 2-24-2018 forward will be furnished to OCD-Artesia.

Rusty Klein

Business Operations Specialist A