RECEIVED

, emerge 2 and 2 a	
Submit One Copy To Appropriate District Office State of New Mexico	Form C-103
District I JUN 0.3 2019 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.
	30-015-26477
District II 811 S. First St. DISTRICT PROPERTIESIAO.C.D. OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name SAND DUNE STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SAND DONE STATE
1. Type of Well: X Oil Well Gas Well Other	8. Well Number #7
2. Name of Operator	9. OGRID Number
EOG RESOURCES, INC	7377
3. Address of Operator PO BOX 2267 MIDLAND, TEXAS 79702	10. Pool name or Wildcat
4. Well Location	
Unit Letter M: 660 feet from the SOUTH line and 660 feet from the WEST line	
Section 11 Township 19S Range 29E NMPM County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3372' GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	JOB
OTHER: Discrete Location is ready for OCD inspection after P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	ARTER/QUARTER LOCATION OR
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.) All other environmental concerns have been addressed as per OCD rules	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
regieved now lines and pipennes.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure. When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE MAD MADON TITLE: REGULATORY SPE	CIALIST DATE 6/20/2019
	CIALIST DATE 3/30/2011
TYPE OR PRINT NAME: KAY MADDOX E-MAIL: kay_maddox@eogresources.c	om PHONE: _432-686-3658
For State Use Only	,
APPROVED BY: TITLE STATE ME	DATE 6/12/19
Conditions of Approval (if any):	