Submit One Copy To Appropriate Office	ARTESIA DISTRICT	State of New Me	exico	Form C-10	
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 OCT 2 4 2019			ıral Resources	Revised November 3, 201 WELL API NO.	1_
District II				30-015-25471.	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION				5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410 RECEIVED1220 South St. Francis Dr.				STATE STEE	
District IV Santa Fe, NM 8/505			7505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, N 87505	١M				
	NOTICES AND REP	ORTS ON WELLS		7. Lease Name or Unit Agreement Name	_
(DO NOT USE THIS FORM FOR	PROPOSALS TO DRILL O	R TO DEEPEN OR PL	UG BACK TO A	Amoco State A	
DIFFERENT RESERVOIR. USE PROPOSALS.)	"APPLICATION FOR PERI	MIT" (FORM C-101) FO	OR SUCH	8. Well Number	_
1. Type of Well: Oil W	ell Gas Well G	Other		3	
2. Name of Operator	<u> </u>			9. OGRID Number	_
COG Operating LLC				229137	
3. Address of Operator				10. Pool name or Wildcat	
2208 W Main Artesia NM 88210				Artesia; QN-Grbg-SA	
4. Well Location					
Unit Letter A 965 f	Feet from the North line	and 330 feet from t	the East line		
I .	wnship 17S Range 28E				
			RKB, RT, GR, etc.)		
	i i	686' GR			
12. Check Appropriate I	Box to Indicate Nat	ure of Notice, R	eport or Other Da	ta	7
			-		
				EQUENT REPORT OF:	
_			REMEDIAL WORK	<u> </u>	
			COMMENCE DRIL		
FULL OR ALTER CASING	☐ MOLTIPLE CC	JMPL L.	CASING/CEMENT	JOB \square	
OTHER:			│	dy for OCD inspection after P&A	
			ne terms of the Opera	tor's pit permit and closure plan.	_
□ Rat hole and cellar have	been filled and leveled	. Cathodic protection	on holes have been p	roperly abandoned.	
A steel marker at least 4'	' in diameter and at leas	st 4' above ground l	level has been set in o	concrete. It shows the	
OPERATOR NAM	E I FASE NAME W	ELL NUMBED A	DI NUMBED OU	ARTER/QUARTER LOCATION OR	
				N HAS BEEN WELDED OR	
	STAMPED ON THE			THIS BEEN WEEDED ON	
☐ The location has been lev	veled as nearly as possi	ble to original grou	nd contour and has b	een cleared of all junk, trash, flow lines and	l
other production equipment.	Cut off P	ower Pola	Must be re	dievel (5.5.de)	
Anchors, dead men, tie d	lowns and risers have b	een cut off at least t	wo feet below groun	d level.	
				nave been remediated in compliance with	1
from lease and well location	ie Operator s pit perinti	and closure plan.	An now lines, produ	ction equipment and junk have been remove	за
All metal bolts and other	materials have been rer	noved. Portable ba	ses have been remove	ed. (Poured onsite concrete bases do not ha	ve
to be removed.) \mathcal{L}	1. Not R	/ لم مدد	< < l \	ca. (x carea create constant cases de net na	
All other environmental	concerns have been add	dressed as per OCD	crules.		
☑ Tipeffiles and now files i	nave been abandoned n	n accordance with 1	9.15.35.10 NMAC.	All fluids have been removed from non-	
retrieved flow lines and pipeli		1 11 1			
			cal service poles and	lines have been removed from lease and we	;H
location, except for utility's d	istribution intrastructur	e.			
When all work has been comp	oleted, return this form	to the appropriate I	District office to sche	fule an inspection	
	hed.	to the appropriate 2		aute un mopeotion.	
Please sea getagl	fer:				
SIGNATURE					
- /	7	TITLE Re	gulatory Technician	DATE 10/22/2019	
TYPE OF PRINTS AT P	Z	· · · · · · · · · · · · · · · · · · ·	- ,		
TYPE OR PRINT NAME De	Zlilah Flores	· · · · · · · · · · · · · · · · · · ·	gulatory Technician	PHONE: 575-748-6946	
TYPE OR PRINT NAME De. For State Use Only		· · · · · · · · · · · · · · · · · · ·	ores2@concho.com		
	dilah Flores	· · · · · · · · · · · · · · · · · · ·	- ,	PHONE: 575-748-6946	