(June 2015) UNITED STATES <b>PARTASDAD</b> Field Off DEPARTMENT OF THE INFRICTSDAD Field Off BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2			ALAN NON J. LEASE SCHAINU.	Expires: January 31, 2018         5. Lease Serial No.         NMNM03677         6. If Indian, Allottee or Tribe Name         7. If Unit or CA/Agreement, Name and/or No.	
			6. If Indian, Allotte		
			7. If Unit or CA/A		
1. Type of Well Gas Well Other			8. Well Name and I STEBBINS 19	No. FED 204H	
2. Name of Operator     Contact: TAMMY R LINK     MATADOR PRODUCTION COMPANYE-Mail: tlink@matadorresources.com			9. API Well No. 30-015-4416		
3a. Address ONE LINCOLN CENTER 5400 LBJ FREEWAY SUITE 15700 575-627-2465			10. Field and Pool	or Exploratory Area	
DALLAS, TX 75240         4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State	
Sec 19 T20S R29E SESE 210FSL 110FEL 32.552177 N Lat, 104.105633 W Lon			EDDY COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES) T(	O INDICATE NATURE OI	F NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION		TYPE OF	TYPE OF ACTION		
□ Notice of Intent	<ul> <li>Acidize</li> <li>Alter Casing</li> </ul>	□ Deepen □ Hydraulic Fracturing	Production (Start/Resume) Reclamation	☐ Water Shut-Off ☐ Well Integrity	
🛛 Subsequent Report	Casing Repair	New Construction		Other	
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug and Abandon Plug Back	Temporarily Abandon  Production Start  Water Disposal		
determined that the site is ready for 1 BLM Bond NO:NMB001079 Surety Bond NO:RLB0015172	-	GC 11/7 Accepted for record	/19 NMOCD		
Surety Bond NO:RLB0015172	2	Accepted for record	NMOCD		
Production Sundry 6/27/2019 Held Pre-frac meet	ing. MIRU completions equi	oment. NU 7 1/16" master v	alve. Test valve to	RECEIVED	
lower flanges to 9,500 psi cha 7/28/2019 Applied 1,500 psi to integrity test to 5,720 psi for 3	o backside w/pop off set @ 2	2,500 psi, (Good Test). Perf	orming casing 7,000 psi @	NOV 0 5 2019	
15 bpm. 8/10/2019 <u>Begin Frac Stage 1</u> 100 Mesh 9759, 40/70 Mesh	<u>f/14,441</u> ' through Stage 23 101482, 8 clusters per stage	on 8/18/2019 @ 9 <u>,360</u> '. 15 <sup>r</sup> , 41 holes per cluster. Well	% NE Acid 15300, DISTR	ICT/I-ARTESIAO.C.I	
	s true and correct				
14 I bereby certify that the foregoing is	Electronic Submission #490 For MATADOR PRO	1418 verified by the BLM Well DUCTION COMPANY, sent to sing by PRISCILLA PEREZ or	the Carlsbad	VI	
14. I hereby certify that the foregoing is	nmitted to AFMSS for process		CTION ANALYST		
	•				
Cor Name (Printed/Typed) TAMMY F	•		······································		
Cor Name (Printed/Typed) TAMMY F	R LINK	Title PRODU	)19		
Cor Name (Printed/Typed) TAMMY F	R LINK	Title PRODU Date 10/30/20 FEDERAL OR STATE 0	)19	0CIate3 1 20	
Cor Name (Printed/Typed) TAMMY F Signature (Electronic	R LINK Submission) THIS SPACE FOR ed. Approval of this notice does not uitable title to those rights in the su	Title PRODU Date 10/30/20 FEDERAL OR STATE O Title CCEPt twarrant or Jona	DI9 DFFICE USE	OCIate3 1 20	

## Additional data for EC transaction #490418 that would not fit on the form

## 32. Additional remarks, continued

drillout operations begin.

-

ś

8/28/2019 Pressure test coil connector to 2,500 psi, pressure test stack, pump iron and flowback manifold to 8000 psi (Good Test).

8/29/2019 Begin milled plugs 22-18, then begin mill plugs 17-1. Total plug weight of 22 plugs=163.8 lbs.

8/31/2019 Prep location to begin flowback operations. 9/1/2019 Well on flowback @ 10:15 hrs on a 16/64" positive choke. 1250 psi getting back water, no gas or oil. 9/2/2019 Getting trace of oil and gas flowing well through 3 phase separator water to OTT; gas to

1/2/2019 Getting trace of oir and gas howing went inough s phase separator water to OTT, gas to 1/2/2019 Gas to sales @ 10:30 hrs. 2/9/2/2019 NU Cactus Lubricator, 2 7/8" x 7 1/16" 15k tubing hanger w/2 way check test. (Good Test). Depth? on Hog.? 9/10/2019 Turned well to production @ 11:00 hrs. All production flowing to facility. Well off

Flowback.