

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-22030
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name:

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Plug & Abandon <input type="checkbox"/>	2. Name of Operator Yates Petroleum Corporation	3. Address of Operator 105 South Fourth Street - Artesia, NM 88210	4. Well Location Unit Letter P : 990 feet from the South line and 990 feet from the East line Section 22 Township 18S Range 26E NMPM Eddy County	5. Well No. 1	6. Pool name or Wildcat Atoka San Andres
---	--	---	--	------------------	---

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

2-18-2003 - Moved in pulling unit and plugging equipment.  
2-19-2003 - Rigged up pulling unit. Rigged up rod equipment. POOH with rods and pump. Rigged down rod equipment. Nippled down wellhead and nippled up BOP. Rigged up tubing equipment and floor. POOH with 2-3/8" tubing. RIH open ended to 1852'. Circulated hole with plugging mud. Spotted 35 sacks Class C Neat cement from 1852-1450'. POOH. Shut well in for night. WOC.  
2-20-2003 - RIH with tubing - did not tag. Spotted 35 sacks Class C Neat cement from 1852-1450'. POOH. WOC 4 hours. RIH with tubing - did not tag. Spotted 35 sacks Class C Neat cement with 2% CaCl2 and LCM from 1852-1450'. POOH. Shut well in for night. WOC.  
2-21-2003 - RIH with tubing and tagged cement at 1379'. Pulled up hole. Circulated hole with plugging mud. Pulled up hole to 1251'. Spotted 35 sacks Class C Neat cement from 1251-900'. POOH. WOC 4 hours. RIH with tubing and tagged cement at 813'. POOH with tubing. Rigged down tubing equipment. Nippled down BOP. RIH with tubing to 60'. Circulated 15 sacks Class C Neat cement from 60' to surface. POOH. Shut well in for night. WOC.

CONTINUED ON NEXT PAGE:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donna Clack TITLE REGULATORY COMPLIANCE TECH DATE 3-4-03

Type or print name DONNA J CLACK

Telephone No. 505-748-1471

APPROVED BY [Signature] TITLE Wild Sep ID DATE MAY 31 2003  
Conditions of approval, if any:

YATES PETROLEUM CORPORATION  
Joyce HG #1  
Section 22-T18S-R26E  
Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

2-22-24-2003 - Hole stayed full. Rigged down pulling unit and plugging equipment.  
Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT.  
Plugging completed February 21, 2003.

Anna Clark

48  
3-5-03



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Betty Rivera

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division



OK  
Bartholomew  
as per Gary G  
5/12/03

Yates Petroleum Corporation  
105 South 4<sup>th</sup> Street  
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your Tracyce - G#1 - Sec 22 - T18S - R26E - 30 - C15 - 22030  
Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- ☒ 1. All pits have been filled and leveled.
- ☒ 2. Rat hole and cellar have been filled and leveled.
- ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- ☒ 5. The dead men and tie downs have been cut and removed.
- ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Jim Kwo  
Name  
Drilling Supvr.  
Title

Date:  
5/9/03

Van Barton  
Field Rep. II