<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 June 1, 2004

For drilling and production facilities submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

MAR - 8 2007

Pit or Below-Grade Tank Registration or Closure

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes \(\subseteq \) No \(\subseteq \) Type of action: Registration of a pit or below-grade tank \(\subseteq \) Closure of a pit or below-grade tank \(\subseteq \)								
Operator: CHESAPEAKE OPERATING. INC. Telephon. Address: P. O. BOX 11050 MIDLAND. TEXAS 79702- Facility or well COMANCHE HILL 18 FEDERAL WELL 001 API #: 30 County: CHAVES Latitude Surface Owner: Federal X State Private Indian	-8050	Sec 18 T 10S R 26E						
Pit Type: Drilling ☑ Production ☐ Disposal ☐ Workover ☐ Emergency ☐ Lined ☑ Unlined ☐ Liner type: Synthetic ☑ Thickness 12mil Clay ☐ Pit Volume 12,139 bbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes							
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.) 70'	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points) (0 points) 0						
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.) Distance to surface water: (horizontal distance to all wetlands, playas.	Yes No	(20 points) (0 points) 0						
irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points) (0 points) ()						
	Ranking Score (Total Points)	0						
If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite offsite from If offsite, name of facility								
Additional Comments:	1010.							
A SIDE DEEP BURIAL TRENCH WAS EXCAVATED NEXT TO THE PIT. THE TRENCH WAS LINED WITH A 20 MIL SYNTETIC LINER. THE PIT CONTENTS WERE THEN PLACED INTO THE LINED TRENCH. THE SIDES OF THE TRENCH WERE FOLDED OVER THE CONTENTS AND A TOP COVER OF 20 MIL SYNTHETIC LINER WAS SEWED IN PLACE. THREE FEET OF TOP SOIL WAS PLACED ON TOP OF THE								
LINED TRENCH AND COMPACTED. THE ORIGINAL PIT WAS BACKFILLED WITH CLEAN SOIL, COMPACTED, AND LEVELLED TO GRADE. CONFIRMATION SAMPLES WERE TAKEN FROM THE EXCAVATED PIT PRIOR TO BACKFILLING AND ARE ATTACHED. THE PIT CLOSURE WAS STARTED ON FEBRUARY 8, 2007 AND COMPLETED ON FEBRUARY 28, 2007.								
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan .								
Date: 3/8/07CLIFF BRUNSON, PRESIDENT, BBC INTL. Printed Name/Title	Signature_Cliff P. Tunan FOR	CHESAPEAKE OPERATING, INC						
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or								
Approval: Printed Name/Title	NMOCD Signature	Date: MAR 0 8 2007						



PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS. NM 88240



ANALYTICAL RESULTS FOR BBC INTERNATIONAL, INC. ATTN: CLIFF BRUNSON P.O. BOX 805 HOBBS, NM 88241

FAX TO: (505) 397-0397

Receiving Date: 02/26/07 Reporting Date: 02/27/07 Project Owner: NOT GIVEN

Project Name: COMANCHE HILL 18 FED. #1

Project Location: ROSWELL, NM

Analysis Date: 02/27/07 Sampling Date: 02/23/07 Sample Type: SOIL

Sample Condition: COOL & INTACT

Sample Received By: BC

Analyzed By: HM

 \sim

	Cl		
LAB NO. SAMPLE ID	(mg/Kg)		
H12245-1 PIT BOTTOM	< 16		
Quality Control	490		
True Value QC	500		
% Recovery	98		
Relative Percent Difference	0.0		

METHOD: Standard Methods 4500-Cl^{*}B

NOTE: Analysis performed on a 1:4 w:v aqueous extract.

Chemist Morano

07-87-0

Date

H12245

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed weived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.

ARDINAL LABORATORIES, INC.

Company Name: BBC International, Inc.

Project Name: Comanche Hill 18 Fal. #1

OSCAr Fragre

Sample I.D.

Pit Botton

Clitt Brunson

Fax#:

Project Owner:

Project Manager.

city: Hobbs

Phone 🙃

Project #:

Sampler Name:

FOR LIBUSE CHLY

Lab I.D.

Sampler - UPS - Bus - Other:

Address: P.O. Box 805

Project Location: Roswell, wan

397-6318

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

ANALYSI

2111 Beachwood, Abilene, TX 79603 101 East Marland, Hobbs, NM 88240 (915) 673-7001 Fax (915) 673-7020 (505) 393-2326 Fax (506) 393-2476

State: Na Zip: 88241

(G)RAB OR (C)OMP

CONTAINERS GROUNDWATER WASTEWATER

397-0397

S REQUEST										
1										
				L						
j						<u></u>				

Page / of /

30 days part that at the rate of 24% per acreum born the original data of handon, and at costs of considers, helicity attorney's lass. striction of accession acting out of ar reserved to the performance of services beneated by Cardenie, repetitions of whether such darks is based upon any of the moves strated towards or otherwise. Phone Result: □ Yes ☐ No | Add'| Phone #: Received By: Fax Result: ☐ Yes □ No Add'l Fax #: REMARKS: Date: Received By: (Lab Staff) Time: Sample Condition Cool Intact Delivered By: [Circle Qne) (initials)

BILL TO

SAMPLING

DATE

2/23/07 9: MA

TIME

Zlp:

P.O. #:

Attn:

City:

Company:

Address:

Phone #:

PRESERY.

ACID/BASE: ICE / COOL

Fax #:

MATRIX

CRUDE OIL

Yes Yyes

† Cardinal cannot accept verbal changes, Please fax written changes to 505-393-2476.