

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUN 18 2007  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

30-015-25758

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Jesse A. Sosa
Address 3300 N. "A" St., Bldg. 6 #247 Midland, TX 79705-5	Telephone No. (505)391-3126
Facility Name James A State well # 3	Facility Type Water Injection
Surface Owner KENNETH SMITH INC	Mineral Owner ConocoPhillips
Lease No. K-3271	

LOCATION OF RELEASE



Unit Letter K	Section 2	Township 22 South	Range 30 East	Feet from the 1980	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
------------------	--------------	----------------------	------------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 30 25.153 N Longitude 103 51.197 W

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 19 BBLs	Volume Recovered 0 BBLs
Source of Release 2" Steel line	Date and Hour of Occurrence 6/6/07 6:30 am	Date and Hour of Discovery 6/6/07 6:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* The leak was in a 2" steel 45. The line was shut in for repair. No produced water was recovered		
Describe Area Affected and Cleanup Action Taken.* Contaminated area consists of approximately 1925 sq ft. of pasture land. The site will be delineated to determine necessary cleanup action.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Jesse A. Sosa	Approved by District Supervisor: 	
Title: HSER Lead	Approval Date:	Expiration Date:
E-mail Address: Jesse.A.Sosa@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06/07/2007 Phone: (505)391-3126		

\* Attach Additional Sheets If Necessary