

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141

Revised June 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate

District Office in accordance



with Rule 116 on back

side of form.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company		Apache Corporation		Contact		Guinn Burks		
Address		P.O. Box 728		Crane, TX 79731		Telephone No. 432-556-9143		
Facility Name		Bright #4 Battery		Facility Type		Tank Battery		
Surface Owner		State of NM		Mineral Owner		BLM		API No. 30-015-28556
LOCATION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from North Line	Feet from West Line	Longitude-W	Latitude-N	County
F	21	21S	23E	1650	1650	104.6109	32.4671	Eddy
NATURE OF RELEASE								
Type of Release				Volume of Release		Volume Recovered		
Produced Water				Less than 3 bbl		0 bbl		
Source of Release				Date and Hour of Occurrence		Date and Hour of Discovery		
Produced Water Flowline				5/17/07 10:30 AM		5/17/07 10:30 AM		
Was Immediate Notice Given?				If YES, To Whom?				
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> Not Required				NMOCD - Artesia Mike Bratcher				
By Whom?				Date and Hour				
Guinn Burks				5/17/07 12:30 PM				
Was a Watercourse Reached?				If YES, Volume Impacting the Watercourse				
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO				NA				
If a Watercourse was Impacted, Describe Fully*								
Describe Cause of Problem and Remedial Action Taken. *								
Flow line leak due to internal corrosion. Two contaminated flow paths were excavated and soil was placed on plastic liner.								
Describe Area Affected and Cleanup Action Taken. *								
Two distinct flow paths within ~30' X 40' area on north side of battery. Clean soil between the flow paths was excavated and a 12-mil plastic liner was installed at the 18" bgs level. Liner was covered with clean soil. Excavated contaminated soil was removed to approved landfarm.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
Signature:				OIL CONSERVATION DIVISION				
								
Printed Name:				Approved by District Supervisor:				
Guinn Burks				BT				
Title:				Approval Date:				
Environmental Coordinator - Permian Basin				JUL 10 2007				
E-Mail Address:				Expiration Date:				
Guinn.Burks@apachecorp.com				Conditions of Approval:				
Date: 7/3/2007 Phone: 432-556-9143				<input type="checkbox"/> Attached				